Maui - Aquifer Sector 03




Table 5-3.57 Ground Water Contamination Summary

Hydrogeologic Setting (1)
Spatial Description (optional) (2)

Island of Maui - 0301 Central Aquifer Sector, Kahului Aquifer System

Map Available (optional) (3)

Map available

Data Reporting Period ⁽⁴⁾ April 1998 - April 2000

Data Reporting		<u> </u>	10111 2000	Ī	1			1	
Source Type (5)	Number of sites (6)	Number of sites with confirmed ground water contamination (6)	Number of sites that are listed and/or have confirmed releases (6)	Contaminants	Number of site investigations (optional)	Number of sites that have been stabilized or have had the source removed (optional)	Number of sites with corrective action plans (optional)	Number of sites with active remediation (optional)	Number of sites with cleanup completed (optional)
NPL	0	0	0						
CERCLIS (non-NPL)	2	0	2	uncertain			2		
DOD/DOE	0	0	0						
LUST	35	0	35	uncertain			35		
RCRA Corrective Action	0	0	0						
Underground Injection	1	0	0						
State Sites	0	0	0						
Non-point source	1	0	1	various			1		
Other (specify)									

NPL - National Priority List

CERCLIS (non-NPL) - Comprehensive Environmental Response, Compensation, and Liability Information System

DOE - Department of Energy

DOD - Department of Defense

LUST - Leaking Underground Storage Tanks

Table 5-3.58 Ground Water Contamination Summary

Hydrogeologic Setting (1)
Spatial Description (optional) (2)

Island of Maui - 0302 Central Aquifer Sector, Paia Aquifer System

Map Available (optional) (3)

Map available

Data Reporting Period ⁽⁴⁾ April 1998 - April 2000

Data Reporting		<u> </u>	10111 2000	1	1			1	
Source Type (5)	Number of sites (6)	Number of sites with confirmed ground water contamination (6)	Number of sites that are listed and/or have confirmed releases (6)	Contaminants	Number of site investigations (optional)	Number of sites that have been stabilized or have had the source removed (optional)	Number of sites with corrective action plans (optional)	Number of sites with active remediation (optional)	Number of sites with cleanup completed (optional)
NPL	0	0	0						
CERCLIS (non-NPL)	0	0	0						
DOD/DOE	0	0	0						
LUST	2	0	2	petroleum			2		
RCRA Corrective Action	0	0	0						
Underground Injection	0	0	0						
State Sites	0	0	0						
Non-point source	0	0	0						
Other (specify)									

NPL - National Priority List

CERCLIS (non-NPL) - Comprehensive Environmental Response, Compensation, and Liability Information System

DOE - Department of Energy

DOD - Department of Defense

LUST - Leaking Underground Storage Tanks

Hydrogeologic Setting (1)
Spatial Description (optional) (2)

Island of Maui - 0303 Central Aquifer Sector, Makawao Aquifer System

Map Available (optional) (3)

Map available

Data Reporting Period ⁽⁴⁾ April 1998 - April 2000

Data Reporting		<u> </u>	10111 2000						
Source Type (5)	Number of sites ⁽⁶⁾	Number of sites with confirmed ground water contamination (6)	Number of sites that are listed and/or have confirmed releases (6)	Contaminants	Number of site investigations (optional)	Number of sites that have been stabilized or have had the source removed (optional)	Number of sites with corrective action plans (optional)	Number of sites with active remediation (optional)	Number of sites with cleanup completed (optional)
NPL	0	0	0						
CERCLIS (non-NPL)	0	0	0						
DOD/DOE	0	0	0						
LUST	2	0	2	petroleum			2		
RCRA Corrective Action	0	0	0						
Underground Injection	0	0	0						
State Sites	0	0	0						
Non-point source	0	0	0						
Other (specify)									

NPL - National Priority List

CERCLIS (non-NPL) - Comprehensive Environmental Response, Compensation, and Liability Information System

DOE - Department of Energy

DOD - Department of Defense

LUST - Leaking Underground Storage Tanks

Hydrogeologic Setting (1)
Spatial Description (optional) (2)
Map Available (optional) (3)

Island of Maui - 0304 Central Aquifer Sector, Kamaloe Aquifer System

Map available

Data Reporting Period ⁽⁴⁾ April 1998 - April 2000

Data Reporting		<u> </u>	10111 2000	1	1			1	
Source Type (5)	Number of sites (6)	Number of sites with confirmed ground water contamination (6)	Number of sites that are listed and/or have confirmed releases (6)	Contaminants	Number of site investigations (optional)	Number of sites that have been stabilized or have had the source removed (optional)	Number of sites with corrective action plans (optional)	Number of sites with active remediation (optional)	Number of sites with cleanup completed (optional)
NPL	0	0	0						
CERCLIS (non-NPL)	0	0	0						
DOD/DOE	0	0	0						
LUST	3	0	3	uncertain			3		
RCRA Corrective Action	0	0	0						
Underground Injection	0	0	0						
State Sites	0	0	0						
Non-point source	1	0	1	various					
Other (specify)									

NPL - National Priority List

CERCLIS (non-NPL) - Comprehensive Environmental Response, Compensation, and Liability Information System

DOE - Department of Energy

DOD - Department of Defense

LUST - Leaking Underground Storage Tanks